

State of Utah

# Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

> JOHN R. BAZA Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

# **Inspection Report**

Permit Number:	C0070012
Inspection Type:	PARTIAL
Inspection Date:	Friday, July 29, 2005
Start Date/Time:	7/29/2005 10:00:00 AM
End Date/Time:	7/29/2005 12:30:00 PM
Last Inspection:	Tuesday, June 14, 2005

Inspector: Priscilla Burton, Environmental Scientist III

Weather: sun 95 F

InspectionID Report Number: 686

Accepted by: whedberg 8/4/2005

Permitee: NEVADA ELECTRIC INVESTMENT CO Operator: NEVADA ELECTRIC INVESTMENT CO

Site: WELLINGTON PREPARATION PLANT

Address: 330 E 400 S STE 6, PO BOX 337 SPRINGVILLE UT 84663

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acreages	Mineral Ownership	Types of Operations		
1,573.50	Total Permitted	☐ Federal	☐ Underground		
392.00	Total Disturbed	☐ State	Surface		
	Phase I	☐ County	Loadout		
	Phase II	☐ Fee	<b>✓</b> Processing		
	Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Observed greasewood riparian area; road damage to slurry pipeline pond and silt fence repair below this road; and Dryer pond inflow.

Inspector's Signature	Insr	ector's	Signa	ature
-----------------------	------	---------	-------	-------

Date

Monday, August 01, 2005

Priscilla Burton, Environmental Scientist III

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070012 Inspection Type: PARTIAL

Page 2 of 3 Inspection Date: Friday, July 29, 2005

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		<b>✓</b>	
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>~</b>		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>~</b>		<b>✓</b>	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation	<b>~</b>		<b>✓</b>	
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing	<b>✓</b>		<b>✓</b>	
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Date: Friday, July 29, 2005

## 1. Permits, Change, Transfer, Renewal, Sale

Mr. Collins indicated that he is making progress on completing a report with additional information on owners and controllers for the AVS system, recently requested by the Division.

## 4.b Hydrologic Balance: Sediment Ponds and Impoundments

All ponds are dry except the Dryer Pond. This pond is adjacent to the railroad tracks (Plate F9-177 1 of 2). An 18-inch cement culvert beneath the railroad tracks is the source of water flowing into the pond at perhaps 1 gpm. Although the culvert outlet could be seen, the inlet could not be found. The water is constant and reliable as evidenced by the established cattails. The pond as-built, Plate A9-1464, does not show the culvert. Mr. Collins speculates that the culvert was buried before pond reconstruction in the late 1990's and that the source of water flowing in the culvert is from irrigation drainage. It is recommended that the hydrologist assigned to the site investigate the source of flow.

## 4.c Hydrologic Balance: Other Sediment Control Measures

Silt fence along the Siaperas ditch is aging. The hydrologist assigned to the site should evaluate the need for this fencing and determine whether the fence should be replaced or removed entirely.

Silt fence repair downstream from the slurry pipeline access road was attempted, but not adequate. The silt fence is not anchored into the ground and will allow flow to pass through. Mr. Collins indicated that this fence would be repaired so that it will function as designed. He plans to complete the repair in two weeks time, when a load of fill will be dellivered to the site.

## 13. Revegetation

The greasewood reference area was observed and photographed. Mr. Collins indicated that this reference area is for lowland reclamation sites, but not for the river pumphouse which was apparently too small to require comparison with a reference area.

Grasses are emerging in the bottom of gouges at the river pump house reclamation site.

# 16.a Roads: Construction, Maintenance, Surfacing

A contractor has been scheduled to repair the erosion on the slurry pipeline road in two weeks from the date of this inspection.